Property Inspection Service

(800) 494-8998 www.EliteInspections.com Servicing Northern and Southern California Industry Leaders in Technology Service...

...is our Product!

PROPERTY INSPECTION REPORT



View Of The Front

ADDRESS: 4031 Bennett Ave Corona California

CLIENT: David & Lori Evans

DATE OF INSPECTION: 4/30/2018 AGENT:

AGENCY/CITY: .

INSPECTOR: Steve Coulter JOB#: 141844

YEAR BUILT: <u>2000</u> REPORT#: <u>14184421</u>

INSPECTION AGREEMENT

BY ACCEPTANCE OF OUR INSPECTION REPORT YOU AGREE TO THE TERMS OF THIS AGREEMENT AND THE TERMS AND CONDITIONS OF THE CONTRACT

SCOPE OF THE INSPECTION / REPORT

We will perform a non-invasive physical examination designed to identify material defects in the systems, structures, and components of buildings located on the property to be inspected, as they exist at the time of the inspection. Our inspection will be limited to those specific systems, structures and components that are present and visually accessible. We will only operate components and systems with normal user controls and as conditions permit. Unless we agree otherwise, we will only inspect the primary building, and its associated primary parking structure, on the property. We will also give you a written report that describes and identifies the inspected systems, structures and components and identifies material defects. We may amend the report within twenty-four (24) hours after completing the inspection.

Unless we agree otherwise, we will perform the inspection, and issue the report, in accordance with the mandatory parts of the current Standards of Practice (Residential Standards - Four or Less Units) of the California Real Estate Inspection Association ("the CREIA Standards") and subject to the Definitions, Scope, Limitations, Exceptions and Exclusions in the CREIA Standards. Terms in this Agreement have the same meaning as the defined terms in the CREIA Standards. The CREIA Standards are available from our inspector and from CREIA's website: http://www.CREIA.org/.

IF YOU DISCOVER A DEFECT FOR WHICH WE MAY BE LIABLE TO YOU, YOU MUST NOTIFY US AND GIVE US A REASONABLE OPPORTUNITY TO RE-INSPECT THE PROPERTY BEFORE YOU REPAIR THE DEFECT. YOUR NOTICE MUST BE IN WRITING, INCLUDE A SIGNED COPY OF THIS AGREEMENT, AND BE MAILED TO:

Corporate Office The Elite Group Property Inspection Service, Inc Attn: Inspector Supervisor 21700 E Copley Suite 390 Diamond Bar, CA 91765 1(800) 494 - 8998

OUR LIABILITY TO YOU FOR CLAIMS ARISING FROM OUR INSPECTION OR OUR REPORT, WHETHER SOUNDING IN TORT OR CONTRACT, WILL NOT BE MORE THAN THE LESSER OF ACTUAL DAMAGES OR TEN (10) TIMES THE INSPECTION FEE.

TEGPIS AND CLIENT AGREE THAT CLIENT CANNOT FILE A LEGAL ACTION AGAINST TEGPIS OR ITS EMPLOYEES, WHETHER SOUNDING IN TORT OR CONTRACT, MORE THAN ONE YEAR AFTER THE CLIENT DISCOVERS, OR WITH THE EXERCISE OF REASONABLE DILIGENCE SHOULD HAVE DISCOVERED THE BREACH OR MATERIAL DEFECT.

Our report is NOT a warranty of the items inspected. Contact your home warranty company.

CONFLICT OF INTEREST DISCLOSURE AND STATEMENT OF COMMITMENT

Our goal is to provide valuable and unbiased information that helps consumers make informed decisions. A portion of our business may be based on relationships with other professions- real estate sales professionals, lawyers, lenders, vendors, etc., and our reports sometimes conflict with the business interests of these parties. We do not allow these relationships to compromise the integrity of our service. However, they do enable us to deliver more value to our clients. Our reports are intended to accurately reflect our impartial professional opinion, without exception.

YOU MUST PAY THE INSPECTION FEE BEFORE WE CAN DELIVER THE REPORT TO YOU.

BY ACCEPTANCE OF OUR INSPECTION REPORT YOU AGREE TO THE TERMS OF THIS AGREEMENT AND THE CONTRACT.

Property Inspection Service

ABOUT YOUR INSPECTION

In order for you to receive the full value of this inspection, please read the information we have provided.

ALL ITEMS IN RED PRINT ARE OF IMMEDIATE CONCERN TO THIS STRUCTURE; HOWEVER, THE ENTIRE REPORT MUST BE READ FOR FULL DISCLOSURE

During this inspection your inspector did not dismantle equipment, dismantle any structural items, apply stress or destructive testing. Areas that are hidden and/or not readily visible are not covered in this report. Our report is not a guarantee or warranty on the condition of your property or its contents. This report provides an unbiased visual inspection only. The Elite Group Property Inspection Service, Inc. inspections are performed with consideration given to the age of the structure. Items marked good must, in all cases, be considered good for the age of the item. Also, items in less than good condition must be marked as such, even though the condition may be normal for the age and should be inspected by the appropriate licensed contractor. Opinions vary from person to person and this report is the opinion of the inspector and must be considered as such. Your report does not include all items covered in the **REAL ESTATE TRANSFER DISCLOSURE FORM.**

An attorney and/or real estate broker should be consulted on additional items not included in this report.

Mold spores cannot be identified as toxic/dangerous with this inspection report. Your inspector is not certified to identify toxic mold spores. It's recommended the client have the property tested by a certified mold inspector, whether or not a mold like substance has been indicated in this report.

PHOTO DOCUMENTATION

Your report also includes digitally imaged photos of certain problem areas (should they exist). Also included are pictures (General Views) to establish location and identification.

TERMS USED IN THIS REPORT

NLC	Normal Living Condition	ELECT.	Electrical
NFAM	Normal For Age of Material	A/C	Air Conditioning
NFTC	Normal For Type of Construction	INT.	Interior
NFAS	Normal For Age of Structure	EXT.	Exterior
NTBS	Not To Building Standards	G.F.C.I.	Ground Fault Circuit Interrupter
GV	General View, establishes location	T.P.R.V.	Temperature Pressure Relief Valve
	and identification	PSI	Pounds per Square Inch
COS	Cosmetic	N/A	Not Accessible / Did Not Inspect
\mathbf{SM}	Small	REC.	Recommend
LG	Large	PRV	Pressure Relief Valve
APPROX.	Approximately	SYST.	System

THIS REPORT IS NON-TRANSFERABLE TO ANOTHER PARTY, NO EXCEPTIONS.

THANK YOU FOR USING THE ELITE GROUP PROPERTY INSPECTION SERVICE, INC.

The Elite	C		
Property Inspection	on Service INTERIOR buyer not present during inspection		
	Includes: living room, family room, dining room, hallways, entry		
l. WALLS	Constructed of / wall coverings: drywall		
Good Fair Poor	patched areas throughout, some wall areas N/A due to personal décor		
✓ ✓ U N/A None			
IN/AINOILE	A/C-Heater: none		
	Wet Bar: none		
	Stairs/rails: none		
	Utilities: Power off Water off Gas off Includes all areas of the structure.		
	✓ Structure occupied: personal items prevent complete inspection throughout the property.		
. CEILINGS			
	Constructed of / ceiling coverings: drywall		
Good Fair Poor	patched areas throughout		
N/A None			
. FLOORS	Floor coverings: ceramic tiles, wood		
Good Fair Poor	stained and worn-COS		
5000 Fair Poor			
N/A None			
	Constructed of almost and built age		
. WINDOWS	Constructed of: aluminum double pane		
Good Fair Poor	condensation-N/A dirty windows, worn frames-NFAM, worn hardware, could not access all		
N/A None			
	A/C-Heater: none		
	Security Bars: none		
5. DOORS	functional, loose/worn hardware, weathered		
Good Fair Poor			
N/A None	Screen Doors: none		
	Closets/Cabinets: functional, normal wear, most N/A due to personal items		
6. SLIDING	tempered glass, worn hardware, worn rollers, worn tracks		
DOOR	tempered glass, worn nardware, worn rollers, worn tracks		
Good Fair Poor			
N/A None	Canaan Daawa nana		
N/A None	Screen Doors: none		
. FIREPLACES	1. Living Room switch ignition		
Good Fair Poor			
✓ □ □	operated		
N/A None			
B. ELECTRICAL	some outlets N/A, some switches N/A, worn switches, worn outlets		
Good Fair Poor	irregular workmanship on fan/overhaed fixture		
N/A None	C.P. E. Service		
	Ceiling Fans: operated		
	Smoke Detectors: operated		
	Carbon Monoxide Detector: operated		
	Door Bell: operated front		

The Elite G	Group		
Property Inspection	Service BEDROOMS		
1. WALLS	Locations: 1. Master 2. North West 3. North Central 4. South 5. North East		
Good Fair Poor			
	Constructed of / wall coverings: drywall		
□N/A □None	patched areas throughout, some wall areas N/A due to personal décor		
	A/C-Heater: none		
	Wet Bar: none		
2. CEILINGS	Constructed of: drywall		
Good Fair Poor			
	Large stained areas-5		
□N/A □None			
3. FLOORS	Floor coverings: carpet		
Good Fair Poor	stained and worn-COS		
N/A None			
4. WINDOWS	Constructed of: vinyl double pane, aluminum double pane		
Good Fair Poor	condensation-N/A dirty windows, worn frames-NFAM, worn hardware, could not access all		
N/A None			
A/C-Heater: none			
	Security Bars: none		
	Salari, Euro, Salari		
5. DOORS	functional, loose/worn hardware		
Good Fair Poor			
✓ ✓ □ □N/A □None			
	Closets/Cabinets: functional, normal wear, most N/A due to personal items		
6. SLIDING	tempered glass, worn hardware, worn rollers, worn tracks		
DOOR			
Good Fair Poor			
✓ ✓ □ □N/A □None	Screen Doors: operated		
7. FIREPLACES			
Good Fair Poor			
N/A ✓ None			
8. ELECTRICAL	most electrical N/A, worn switches, worn outlets		
Good Fair Poor			
✓ ✓ □ □N/A □None			
IVA	Ceiling Fans: operated		
	Smoke Detectors: operated		
	Carbon Monoxide Detectors: none		
	The city of Los Angeles requires smoke detectors in all bedrooms.		

The Elite	Group
Property Inspection	
- •	BATHROOMS
1. WALLS Good Fair Poor N/A None	Locations: 1. Master 2. Hall Constructed of / wall coverings: drywall patched areas throughout, some wall areas N/A due to personal décor
2. CEILINGS Good Fair Poor N/A None	Constructed of: drywall patched areas throughout
3. FLOORS Good Fair Poor N/A None	Floor coverings: ceramic tiles stained and worn-COS, area rugs present
4. WINDOWS Good Fair Poor N/A None	Constructed of: aluminum double pane worn frames-NFAM, worn hardware, condensation-N/A dirty windows Security Bars: none
5. DOORS Good Fair Poor N/A None	functional, loose/worn hardware
6. COUNTERS Good Fair Poor N/A None	normal wear-1, under construction-N/A-2
7. CABINETS Good Fair Poor N/A None	functional, normal wear, most N/A due to personal items-1, under construction-N/A-2
8. SINKS Good Fair Poor N/A None	functional, worn fixtures-1, under construction-N/A-2
9. MIRRORS Good Fair Poor N/A None	functional

The Elite G	roup
Property Inspection	
10. BATH TUBS Good Fair Poor N/A None	normal wear Leaking overflow drains and spa tub jet hoses cannot be detected with this inspection.
11. SHOWERS Good Fair Poor N/A None	normal wear
12. SHOWER WALLS Good Fair Poor N/A None	normal wear
	tempered glass, normal wear
14. TOILETS/ BIDETS Good Fair Poor N/A None	worn units
15. PLUMBING Good Fair Poor ✓ ✓ □ □N/A □None	under construction-N/A-2
16. ELECTRICAL Good Fair Poor N/A None	some outlets N/A, some switches N/A, worn switches, worn outlets GFCI: test operated Exhaust Fans: operated
17. HEATING Good Fair Poor N/A None	Type: central unit

The Elite	Group	
Property Inspection Service KITCHEN		
1. WALLS Good Fair Poor V V N/A None	Constructed of / wall coverings: drywall patched areas throughout, some wall areas N/A due to personal décor	
	✓ appliances prevent complete inspection of walls and floors.	
2. CEILINGS Good Fair Poor ✓ ✓ □ □N/A □None	Constructed of: drywall patched areas throughout Ceiling Fan: none	
3. FLOORS Good Fair Poor N/A None	Floor coverings: ceramic tiles stained and worn-COS, area rugs present	
4. WINDOWS Good Fair Poor N/A None	Constructed of: aluminum double pane condensation-N/A dirty windows, worn frames-NFAM, worn hardware	
	Security Bars: none	
5. DOORS Good Fair Poor N/A None		
6. COUNTERS Good Fair Poor V V N/A None	normal wear	
7. CABINETS Good Fair Poor N/A None	functional, normal wear, most N/A due to personal items	
8. SINKS Good Fair Poor	functional, worn fixtures	
N/A None	Spray Wand: operated	
	Drinking Water Faucet: operated	
	Hot Water Dispenser: none	
	Soap Dispenser: none	

The Elite G	roup
Property Inspection	
9. DISHWASHER	operated, not fully visible due to dishes, worn unit
Good Fair Poor	
N/A None	This inspection cannot determine how well the dishwasher cleans the dishes
10. DISPOSAL	operated, worn unit
Good Fair Poor	
N/A None	Blades are not inspected
11. PLUMBING	personal items prevent complete inspection
Good Fair Poor	
N/A None	Water purifying systems and water softners are not inspected.
12. RANGE	Number of burners that did not operate: 0 Number of burners that did not self light: 0
Good Fair Poor	operated, gas
✓ ✓ □ □ N/A □ None	
13. OVEN Good Fair Poor	operated, gas
N/A None	
	Microwave Oven: operated
	Trash Compactor: operated
14. VENTING	Type: hood with fan
Good Fair Poor	operated
✓ □ □ □ □ N/A □ None	
	some outlets N/A, some switches N/A, worn switches, worn outlets
15. ELECTRICAL Good Fair Poor	Some outlets IVA, some switches IVA, worm switches, worm outlets
□N/A □None	
	GFCI: test operated
	Non built-in appliances and built-in refrigerators are excluded from this report.
16. SLIDING	
DOOR Good Fair Poor	
	Screen Door: none
N/A ✓ None	SCIECH DOOL, HORE

The Elite G	roup			
Property Inspection	Service	LAUNDRY AREA	see interior hall area	
1. WALLS Good Fair Poor N/A None	Constructed of / wall co	verings: N/A	✓ Washer and dryer prevent complete inspection	on.
2. CEILINGS Good Fair Poor N/A None	Constructed of: N/A		(V) A MONEY MILE MAYOR PROVINCE COMPLETE INSPECTION	,
3. FLOORS Good Fair Poor N/A None	Floor coverings: N/A			
4. WINDOWS Good Fair Poor N/A None	Constructed of: N/A Security Bars: N/A			
5. DOORS Good Fair Poor N/A None	Counters/Cabinets: N/A	A		
6. DRYER VENT Good Fair Poor N/A None	could not access-N/A			
7. PLUMBING Good Fair Poor N/A None	Laundry Tub/Sink: non Water supply valves that a do not shut off completely	e are left in the on position for a l	long period of time tend to leak when turned off or d whether a washing machine is present or not.	
8. GAS VALVE Good Fair Poor N/A None	not visible-N/A			
9. ELECTRICAL Good Fair Poor ✓ □ □ □ N/A □ None	some outlets N/A, some s GFCI: none visible	switches N/A		
	Exhaust Fan: operated			

The Elite G	roup
Property Inspection	
1. STRUCTURE	
Good Fair Poor	cracked,loose & worn lumber
N/A None	
2. INSULATION	Material type: loose fill approximate depth: 6"
Good Fair Poor	
✓ □ □ □ N/A □None	
	Note: The inspector cannot determine or test if asbestos materials exist in the structure.
3. VENTILATION	
Good Fair Poor ✓ □ □	
N/A None	Vent Screens: functional
	Temperature sensors and fans for attic exhaust systems are not tested.
4. EXHAUST	loose & worn areas
VENTS	
Good Fair Poor	
N/A None	
5. DUCT WORK	loose connections & worn areas
Good Fair Poor	
N/A None	
6. ELECTRICAL	most N/A due to insulation
Good Fair Poor	
✓ □ □ □ □ N/A □ None	
	was N/A due to involution in an atom we will in an atim a trie when him
7. PLUMBING	most N/A due to insulation, inspector ran water while inspecting attic plumbing
Good Fair Poor	
N/A None	
8. ACCESS	functional
Good Fair Poor	
✓ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □	
□N/A □None	
9. CHIMNEYS	direct vent
Good Fair Poor	
✓ N/A None	

The Elite (
Property Inspection	n Service HEATING/AIR CONDITIONING			
1. HEATER	Location: 1.Attic Type: gas, forced air, split system This report does not indicate if the heater is on recall, a follow up report will be emailed thru RecallChek.			
2. CONDITION	operated, dirty/dusty unit-recommend cleaning			
3. FILTERS Good Fair Poor N/A None	Approx. Filter size: 24x 30 x 1 Filter location: hall ceiling Electronic air filters are not inspected. Inspector cannot determine a crack in the fire box.			
4. THERMOSTAT Good Fair Poor N/A None	${f S}$ operated $ {f Radiant\ heating\ system\ not\ tested} $			
5. GAS VALVES Good Fair Poor N/A None	functional			
6. VENTING Good Fair Poor N/A None	normal wear			
7. AIR SUPPLY Good Fair Poor N/A None	recommend cleaning return air chambers			
8. REGISTERS Good Fair Poor N/A None	Heater Temperature at Registers: 87 Temperature at Air Return: 66 A/C Temperature at Registers: 48 An Average Temerature Reading is taken throughout structure Not all registers can be tested for air flow pressure, due to location, condition and operation of heater and A/C.			
9. ENCLOSURE Good Fair Poor N/A None				
10. A/C COMPRESSOR Good Fair Poor	Location: 1.exterior grounds Type: electric operated, dirty coils			
N/A None	Refrigerant Lines: functional Gas A/C units and swamp coolers are not inspected.			

The Elite G	roup			
Property Inspection	Service	WATER HE	ATER	
1. CONDITION	Locations: 1.Garage Type: gas operated			Number of gallons: 50
				Solar heating systems are not inspected.
2. VENTING				
Good Fair Poor ✓ □ □ N/A □ None				
3. PLUMBING Good Fair Poor	Material type: copper slight corrosion present			
□N/A □None				
4. TPRV Good Fair Poor N/A None				
5. OVERFLOW LINE Good Fair Poor N/A None	Material type: copper			
6. STRAPPING Good Fair Poor ✓ □ □ □ N/A □ None	strapped properly			
7. GAS VALVE Good Fair Poor N/A None	rec. drip line			
8. BASE Good Fair Poor N/A None	worn areas & mold like s	ubstance present		
9. COMBUSTION Good Fair Poor N/A None				
10. ENCLOSURE Good Fair Poor □ □ □ □ N/A ✓ None				

The Elite (Group
Property Inspection	GARAGE/CARPORT
	garage roof attached to main structure-see roof page, most N/A due to personal items
1. ROOF AREA	Constructed of: N/A
CONDITION	
Good Fair Poor	
□ □ □ □ □ ☑ N/A □ None	Rafters/Ceiling: functional, most N/A due to personal items
VIVA None	
2. MAIN DOOR	Type: sectional door weathered
Good Fair Poor	weathered
N/A None	
3. HARDWARE/	rusted & worn areas
SPRINGS	
Good Fair Poor	
	Utility Tub/Sink: none
N/A None	
4. OPENER	operated, worn unit
Good Fair Poor	
N/A None	Automatic Reverse: operated
5. DOORS Good Fair Poor	Fire Door: functional
	Man Door: functional, loose/worn hardware, weathered
N/A None	Screen Door: none
	personal items prevent complete inspection, patched areas
6. FIREWALL/ WALLS	personal items prevent complete hispection, patched areas
Good Fair Poor	Anchor Bolts: not visible
N/A None	Counters/Cabinets: most N/A due to personal items, worn
7. SLAB	personal items prevent complete inspection
Good Fair Poor	
N/A None	
8. ELECTRICAL	some outlets N/A, some switches N/A, worn switches, worn outlets
Good Fair Poor	exposed below 8 feet
N/A None	GFCI: none visible
	220V: none visible
9. VENTILATION	could not access due to personal items
Good Fair Poor	
☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Windows: none

The Elite (Group Control of the						
Property Inspection Service ROOF							
Inspector did not walk on	a roof, inspected from ladder/ground only, Some areas not visible due to height/angle/solar panels						
1. CONSTRUCTED	O OF: tile						
2. CONDITION	cracked and chipped tiles-NFAM, loose mortar, evidence of past leaking consult seller						
Good Fair Poor N/A None							
3. FLASHINGS	rusted, bent, lifting						
Good Fair Poor N/A None							
4. GUTTERS/	loose connections,worn areas						
DOWN SPOUT Good Fair Poor N/A None							
5. VENTS/	loose caps, rusted						
VENT CAPS Good Fair Poor V V □ N/A None							
6. CHIMNEYS	normal wear, direct vent						
Good Fair Poor ✓ ✓ □ N/A None							
7. SPARK	Includes all exterior accessible areas of the chimney. Interior cavity excluded from inspection report. rusted & worn						
ARRESTORS	rusted & worm						
Good Fair Poor ✓ ✓ □ □N/A □None							
8. SKYLIGHTS							
Good Fair Poor N/A None							
9. WEATHER CONDITION	overcast and cloudy, cold, drizzle						
10. COMMENTS							
	Solar panels/tube globes excluded from report. The inspector cannot determine whether a roof is water tight or not						

The Elite	Group					
Property Inspection Service ELECTRICAL SERVICE						
1. PANELS Good Fair Poor N/A None	Location: Main Panel: west side loose worn covers, unused wires present Electrical/gas fires due to poor installation of wiring and gas lines cannot be determined by the inspector.					
2. BREAKERS Good Fair Poor N/A None 3. FUSES	Number of breakers in off position: 0 Breaker Amp Rating: 100 loose/worn breakers Type of Wiring: copper Fuse Amp Rating: N/A Number of fuses burnt out: 0					
Good Fair Poor N/A None						
4. FEEDS Good Fair Poor N/A None	underground EXCEPTION INC.					
5. STUCCO Good Fair Poor N/A None	small cracking-COS, chipping, small holes Weep Screed:					
6. SIDING Good Fair Poor N/A None	Constructed of: wood, stucco over foam cracked, weathered For damaged wooden areas and moisture problems (mold/mildew), consult the termite inspection report.					
7. EAVES/FACIA Good Fair Poor N/A None	stained, cracked, weathered					
8. PAINT Good Fair Poor N/A None	fading					
9. DOORS/ WINDOWS Good Fair Poor V V □ □N/A □None	Doors: weathered Windows: weathered See interior for additional information					
10. MAIN GAS VALVE Good Fair Poor N/A None	Location: west side natural gas Seismic Safety Valve Present: ☐ Yes ✓ No Gas leaks or carbon monoxide poisoning cannot be detected with this inspection, including all gas/propane systems interior and exterior of the structure. Obstructed gas appliance ventilation exhaust pipes cannot be detected. Recommend Gas Company to evaluate all gas areas before occupying the property. Fire pits and exterior BBQ's are excluded from this inspection. Recommend mold/moisture problems/damage be further evaluated by the appropriate licensed contractor.					

The Elite G	roup
Property Inspection	Service GROUNDS
1. DRIVEWAYS Good Fair Poor N/A None	Constructed of: concrete Includes driveways, walkways, patios, porches, decks and pool areas should they exist. cracked-NFAM
2. PATIO/PORCH ROOFS	Constructed of: shade type aluminum
Good Fair Poor N/A None	bent & worn areas Can not determine if patio/porch roofs are water tight.
3. PATIO ENCLOSURE Good Fair Poor N/A None	Balcony: none
	For damaged wooden areas and moisture problems (mold/mildew), consult the termite inspection report.
4. SLAB/DECKS Good Fair Poor N/A None	Ext. stairs/handrails: none
5. ELECTRICAL Good Fair Poor N/A None	worn outlets & fixtures GFCI: none visible Low voltage lighting and motion detected lights are not inspected.
6. MAIN WATER VALVE Good Fair Poor V V N/A None	Location: front of structure worn valve Type of Plumbing: Copper: 10% Polyethylene Tubing: 20% Unknown: 70% APPROX.%
7. WATER PRESSURE Good Fair Poor N/A None	Approximate pounds per square inch: 110+ high pressure, recommend 55-80 pound per square inch Pressure Regulator: present see water pressure
8. SPRINKLERS Good Fair Poor N/A None	on timers-not inspected Sprinklers on timers are not inspected consult seller/association.
9. FENCING/ WALLS Good Fair Poor N/A None	Constructed of: block, wood damaged wood Gates: functional
10. GRADING Good Fair Poor N/A None	Planters: functional exposed tree roots & rec. removal of shed Above ground pools, ponds, waterfalls, birdbaths, and pumps used for these items, are excluded from this report. Steep hillsides and
LIVA LIVILE	inaccessible areas on the grounds are excluded from this report.

The Elite (Froup
Property Inspection	Service FOUNDATION
SLAB FOUNDATION 1. SLAB Good Fair Poor \[\sum_N/A \sum_None \]	☐ Living area is above garage/subterranean structure, second story or above concrete slabs can not be inspected. slab not visible due to floor coverings
2. FOUNDATION SLAB PERIMETER Good Fair Poor	not visible
RAISED FOUNDATION 3. VENTILATION Good Fair Poor N/A None	Vent Screens: none Access Cover: none
4. POST/GIRDERS Good Fair Poor □ □ □ □N/A ✓None	
5. SUB FLOORING Good Fair Poor N/A None	
6. FOUNDATION WALLS Good Fair Poor N/A None 7. ELECTRICAL Good Fair Poor N/A None	Anchor Bolts: none Cripple Walls: none Chimney Hearth: none river rock foundation present, recommend contractor to determine stability
8. PLUMBING Good Fair Poor N/A None 9. DUCT WORK	Sump pumps, septic tanks and sewer drain pipes from structure to street are excluded from this inspection.
Good Fair Poor N/A None	



Reference Page: Grounds Reference Area: Fencing/Walls



Reference Page: Heating Air Conditioning **Reference Area:** A/C Compressor



Reference Page: Heating Air Conditioning Reference Area: Refrigerant Lines



Reference Page: Grounds Reference Area: out structure



Reference Page: Exterior Items Reference Area: Main Gas Valve



Reference Page: Electrical Service Reference Area: Main Panel



Reference Page: Grounds **Reference Area:** Main Water Valve



Reference Page: Grounds **Reference Area:** Water Pressure



Reference Page: Grounds Reference Area: tree roots



Reference Page: Grounds Reference Area: Patio Roof



Reference Page: Water Heater Reference Area: General View



Reference Page: Water Heater Reference Area: General View



Reference Page: Water Heater **Reference Area:** Condition



Reference Page: Garage Reference Area: Electrical



Reference Page: Garage Reference Area: general view



Reference Page: Laundry Area Reference Area: General View



Reference Page: Interior **Reference Area:** Fireplaces



Reference Page: Bathrooms Reference Area: General View



Reference Page: Bathrooms Reference Area: General View



Reference Page: Bathrooms Reference Area: General View



Reference Page: Bathrooms Reference Area: General View



Reference Page: Heating Air Conditioning

Reference Area: Registers



Reference Page: Heating Air Conditioning

Reference Area: Registers



Reference Page: Bedrooms **Reference Area:** Ceilings



Reference Page: Heating Air Conditioning

Reference Area: Heater



Reference Page: Heating Air Conditioning

Reference Area: Heater



Reference Page: Attic

Reference Area: General View



Reference Page: Attic

Reference Area: General View



Reference Page: Attic

Reference Area: General View



Reference Page: Attic

Reference Area: General View



Reference Page: Attic

Reference Area: General View



Reference Page: Attic

Reference Area: General View



Reference Page: Attic Reference Area: Structure



Reference Page: Attic Reference Area: Structure



Reference Page: Kitchen Reference Area: General View



Reference Page: Heating Air Conditioning

Reference Area: Registers




Reference Page: Interior Reference Area: General View



Reference Page: Interior Reference Area: General View



Reference Page: Bedrooms Reference Area: General View



Reference Page: Bedrooms **Reference Area:** General View



Reference Page: Bedrooms Reference Area: General View



Reference Page: Bedrooms Reference Area: General View



Reference Page: Roof Reference Area: General View



Reference Page: Roof

Reference Area: General View



Reference Page: Roof

Reference Area: General View



Reference Page: Roof

Reference Area: General View



Reference Page: Roof

Reference Area: General View

Reference Page: Reference Area:

Property Inspection Service

(800) 494-8998 www.EliteInspections.com Servicing Northern and Southern California Industry Leaders in Technology

Service...
...is our Product!

PROPERTY INSPECTION REPORT



Rear View

Thank you for using The Elite Group Property Inspection Service, Inc.

We appreciate the business and look forward to serving you in the future.

Property Inspection Service

Report#: 14184421

RESIDENTIA	AL EARTHQUAKE HAZARDS KI	LPUK	1		
Answer these questions to the best of you knowledge have the feature, answer "N/A")	e. If you do not have actual knowledge as to whether the weaknesses exist, a	answer don't k	know. (If your l	nouse does not
1. Is the water heater braced, strapped, or anchored to resist falling during an		Yes	No	N/A	Don't Know
eathquake?		✓			
2. Is the house anchored or bolted t	to the foundation?			✓	
3. If the house has cripple walls:					
Are the exterior cripple walls	braced?			✓	
If the exterior foundation consthey been strengthened?	sists of unconnected concrete piers and posts, have	;		✓	
4. If the exterior foundation, or parbeen strengthened?	t or it, is made of unreinforced masonary, has it			✓	
5. If the house is built on a hillside,	, answer the following:				
Are the exterior tall foundation	on walls braced?			✓	
Were the tall post or columns been strengthened?	s either built to resist earthquakes or have they			✓	
6. If the exterior walls of the house masonary, have they been strengthed	e, or part of them, are made of unreinforced ened?			✓	
7. If the house has living area over opening either built to resist earthq	the garage, was the wall around the garage door uakes or has it been strengthened?	9		✓	
8. Is the house outside an Alquist-F surrounding known earthquake fau	Priolo Earthquake Fault Zone (zones immediately lts)?				V
9. Is the house outside a Seismic haliquefaction or landsliding)	azard Zone? (zone identified as susceptible to				✓
evaluation. If you corrected one or more of these we As seller of the property described herein, I have ans it may have. As buyer of the property, I acknowledge receipt	use is likely to have an earthquake weakness. Questions answered "Don't I eaknesses, describe the work on a sparate page. swered the questions above to the best of my knowledge in an effort to discluding of this form, completed and signed by the seller. I understand that if of knowledge, there may be one or more earthquake weaknesses in	lose fully any	potentia	al eartho	quake weakness
As seller of the property described herein, I have earthquake weakness it may have.	re answered the questions above to the best of my knowledge in an e	effort to dislo	se fully	any po	otential
EXECUTED BY:					
SELLER:	SELLER:	D	ATE:		
BUYER:		D	ATE:		
	e standard real estate transfer disclosure statement also required by law.	INIC (C)	00\ 40	M 004	00
PROVIDED BY THE ELIT	TE GROUP PROPERTY INSPECTION SERVICE,	INC. (8)	uu) 49	4-899	70

Property Inspection Service

SUMMARY PAGE

Inspection Address: 4031 Bennett Ave Corona California

Date of Inspection: 4/30/2018

Client: David & Lori Evans Report#: 14184421

INTERIOR

Electrical: irregular workmanship on fan/overhaed fixture

BEDROOMS

Ceilings: Large stained areas-5

ATTIC

Structure: cracked,loose & worn lumber

WATER HEATER

Base: worn areas & mold like substance present

GARAGE/CARPORT

Electrical: exposed below 8 feet

Fencing/Walls: damaged wood

GROUNDS

Patio/Porch Roof: bent & worn areas

Water Pressure: high pressure, recommend 55-80 pound per square inch

Pressure Regulator: see water pressure

Grading: exposed tree roots & rec. removal of shed