

2878 Dr. Echo Springs Repaired Items

Closet Door

Bottom track broke, purchased and installed new track

Master Bathroom Countertop

Re-caulked side splash of countertop

Water Heater

Reduced water temperature

Water Heater Corrosion

Removed corrosion from shut off valve

Side Metal Gate

Cut off metal where necessary on gate that was too long

Backyard Walkway

Install concrete in front of elevated part of walkway to make a 45 degree fill in to avoid a tripping hazard. Cut roots from tree that went under concrete

Microwave

New Microwave by Hartshorn Appliance

Balcony

Secured loose members and repainted