

## **2878 Dr. Echo Springs Repaired Items**

### Closet Door

Bottom track broke, purchased and installed new track

### Master Bathroom Countertop

Re-caulked side splash of countertop

### Water Heater

Reduced water temperature

### Water Heater Corrosion

Removed corrosion from shut off valve

### Side Metal Gate

Cut off metal where necessary on gate that was too long

### Backyard Walkway

Purchased and install concrete in front of elevated part of walkway to make a 45 degree fill in to avoid a tripping hazard

### Microwave

New Microwave by Hartshorn Appliance

### Balcony

Secured loose members and repainted